


1. COST TO RESET SHALL INCLUDE SAND, DGA, AND ALL LABOR ASSOCIATED WITH THE RESETTING PROCESS.
2. COST TO REPLACE SHALL INCLUDE ALL ITEMS LISTED IN NOTE #1 ABOVE AS WELL AS THE SLATE AS SHOWN IN THE DETAIL.

*SLABS SHALL BE A MINIMUM OF 2" THICK



RESET/REPLACE BLUESTONE SIDEWALK



SLATE SIDEWALK DETAIL

CITY OF SUMMIT UNION CO., N.J.

DIVISION OF ENGINEERING

CITY OF SUMMIT UNION CO., N.J.

DIVISION OF ENGINEERING

DATE:
10/1/2011